



UNDERWATER
DIVING SERVICES

Silloth Outfall Pipeline Survey

In the search for wreckage of a collapsed outfall navigational marker, a 2D Sidescan SONAR was used for target location and a 3D SONAR for detailed examination of wreckage found on the seabed. Very strong tidal currents required that the SONAR be deployed on a seabed tripod.

